

Fig. 1A




Fig. 1B




Fig. 2




Fig. 3

8617L




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8

P7198




Fig. 9




Fig. 10





Fig. 11



8/1/98

Fig. 12




Fig. 13

1402
Form porous Ta block as first electrode of capacitor

1404
Attach a first plurality of terminals to first electrode

1406
Mask portion of terminals

1408
Oxidize exposed Ta

1410
Form a second electrode of capacitor over oxidized Ta

1412
Attach a second plurality of terminals to second electrode

FIG. 14